

IP Devices 541

General Description

Vicon has released an updated IP device package as part of the ViconNet and VMDC version 7.0 release. This new release includes updates for certain firmware versions as well as an updated setup tool.

Included Updates

IP devices 541 includes the following:

1. Updated VNSetup discovery software to version 4.02
2. Firmware updates as listed in the table below

Devices Support and Latest Version

The IP devices supported by this package and their latest firmware software are provided below:

IP Device Type	Former Firmware provided (540)	New Firmware in package 541
SVFT-IP V910 VN-301T	53.0.20.0 Bios 1.0.10.86	53.0.25.0 Bios 1.0.10.86
KTX-4	5.0.30.30	5.0.30.53
V910-PoE VN-855 VN-856 Surveyor-Mini	5.0.5.0	5.0.8.0
KRX-3	5.6.1.10	No change
H.264-4CH-encoder	6.5.2.1	6.6.7.1
H.264-16CH-encoder	6.6.62.1	6.6.67.1

Note:

- This update is not relevant for Vicon MP-955, VND-970IP, V960 and MP-980 cameras.
- VN-755 IP camera is no longer tested after IP cards version 532.

Vicon Release Notes

Updated Features

The following features and functionality are part of the updated firmware:

1. Compatibility with version 7.0 for Surveyor HD and H.264 4- and 16 channel encoders. These products will not be displayed in version 7.0 unless updated.
2. Support quick playback when used with Recording Management (version 7.0) for all ViconNet IP devices.

Who Should Install the New Package?

This software package is a part of ViconNet and VMDC version 7.0 release and its contents is required in order to allow continued operation and support with it. If the system has been updated to ViconNet/VMDC 7.0, this update must be applied along with it (if the affected devices are part of the system).

Obtaining the IP Device 541 Package

This software package can be downloaded from Vicon's website free of charge through the following address:

<http://www.vicon-security.com/support-technical-support-software-downloads.htm>

Licensing

There is no license required to update drivers.