

V9360 series cameras Firmware

General Description

Vicon has released the latest firmware for the V9360 Hemispheric series of cameras.

The updated firmware is as follows:

Camera	Older Firmware	Newest Firmware
V9360	A1D-311-V5.11.17-NB	A1D-311-V5.12.12-NB
V9360W	A1D-311-V5.11.17-NB	A1D-311-V5.12.12-NB

Vicon Production

All cameras in stock will be updated with the new firmware and the files will be made available for download from the product page on the web site.

Problems addressed

This is part of a general update to the camera firmware and is not mandatory.

Installing the Updated Firmware

The latest firmware is available on Vicon's website from the Support tab – Technical Support – Software Downloads – Vicon Network Camera Software; a link is provided below.

<http://www.vicon-security.com/support-technical-support-software-downloads-network-cameras.htm>

You may use the discovery utility provided on the website to perform the update for multiple cameras at a time or update directly from the camera's web interface as described in the camera manual.