

## IP Devices 539

### General Description

Vicon has released an updated IP device package. The new release includes updates for certain firmware versions as well as an updated setup tool.

### Included Updates

IP devices 539 include the following:

1. Updated version (3.9) for VNSetup software
2. Updated firmware for both the 4- and 16-channel H.264 encoders

### Devices Support and Latest Version

The IP devices supported by this package and their latest firmware are provided below:

IP Device Type	Latest Firmware Provided in 539	Changes from Former Package (538)
SVFT-IP V910 VN-301T	53.0.22.0 bios 1.0.10.86	No change
KTX-4	5.0.30.47	No change
V910-PoE VN-855 VN-856 Surveyor-Mini	50.70.0.0	No change
H.264 4CH encoder	6.6.5.1	Updated firmware
H.264 16CH encoder	6.6.62.1	Updated firmware
KRX-3	5.6.1.10	No change

Note:

- This update is not relevant for Vicon I-Onyx 9xx cameras from any series.
- VN755 IP camera is no longer tested after IP cards version 532.

# Vicon Release Notes

---

## Who Should Install the New Package?

This package is **not** a mandatory update and is meant for any user requiring a firmware update or directed to apply one by Vicon.

## Obtaining the IP Device 539 Package

This software package can be downloaded from Vicon's website free of charge through the following address:

<http://www.vicon-security.com/support-technical-support-software-downloads-network-cameras.htm>

The package will added to the next release of ViconNet version 6.x DVD.

## Known Limitation

The following limitations exist and will be corrected in a future version:

1. On certain networks, VNSetup will **not** always detect and list all the cameras. Cameras that are not automatically listed can still be accessed manually.
2. In some cases, VNSetup will report a failure of the device to reboot after changes have been made. A refresh to VNSetup recovers from that situation

## Licensing

There is no license required to update drivers.